

DESCRIPTION



HARDWARE

No.	Item	Detail	Quantity		
1	X	0	x8		
2	Υ		x1		
3	L1	M8x50mm	x8		
4	W		x4		


ASSEMBLY INSTRUCTIONS



IMPORTANT NOTE:

Do not tighten all screws/bolts until all completely assembled. Thank you.


DESCRIPTION



HARDWARE

No.	Item	Detail	Quantity
1	Χ	0	x8
2	Υ		x1
3	L1	M8x50mm	x8
4	W		x4

ASSEMBLY INSTRUCTIONS




IMPORTANT NOTE:

Do not tighten all screws/bolts until all completely assembled. Thank you.

DESCRIPTION


ASSEMBLY INSTRUCTIONS



HARDWARE

No.	Item	Detail	Quantity		
1	X	0	x8		
2	Υ		x1		
3	L1	M8x50mm	x8		
4	W		x4		

Step 1



IMPORTANT NOTE:

Do not tighten all screws/bolts until all completely assembled. Thank you.