











# Galvaniseret højbed

workmann


## 120x60x30CM

<b>A</b> 	<b>B</b> 50cm 	<b>C</b> 55cm 	<b>D</b> 	<b>E</b> 	<b>F</b> 	<b>G</b>  30cm	<b>H</b> 	<b>I</b> 
4STK	2STK	4STK	40+2STK	36+2STK	6+1STK	4STK	1STK	1STK


Trin 1




Trin 2




Trin 3



Trin 4



Trin 5



Installationen er gennemført.

